
ASSEMBLY INSTRUCTION

PARTS INDENTIFICATION				
NO	Part	Sketch	Quantity	
1	Ô	LEG	4PCS	

HARDWARE LIST				
NO	Shape	Specification	Quantity	
Α	000000	Bolt	4pcs	
В	٩	Spring washer	4pcs	
С	0	Flat washer	4pcs	
D	Γ	Wrench	1pc	



Do not tighten screws until completely assembled.