

Step 5 : Affix the angle bracket (O) to both the headboard leg (D) & side wing (N) with screw driver (not provided) as shown .